



Item #: C42BM Assembly Instructions




For our most current instructions, to request missing, lost or broken parts, or for any other Customer Service issues, please visit our website at **www.walkeredison.com** or call us at 877-207-5906.

Revised 03/2012




Hardware List




The hardware quantities listed above are required for proper assembly. Some extra hardware may also have been included.

Step 1




Carefully lay glass (1) up-side-down on a soft surface. Screw long rods (A) into plates of glass (1). Screw short rods (B) into feet (C).

Step 2




Slide cylinders (2) onto long rods (A). Insure that the curved end of each cylinder (2) is facing up as shown above.

Step 3




Insert legs (4) into crossbars (3). Note that it is important for the holes of legs (4) to align with the holes of crossbars (3).

Step 4




Slide the leg assembly from the previous step onto long rods (A).






Place mesh basket (5) onto long rods (A).

Step 6




Secure mesh basket (5) by screwing nuts (D) with washers (E) onto long rods (A). Tighten nuts (D) with wrench (F).





Screw feet (C) into legs (4).

Step 8



Final Assembly