


Assembly Diagram





MODEL NO:C42BM












Α	\odot	Top Glass	1
В	(7" Rod	4
С	•	Cylinder	4
D	000	Cross Bar	2
Е		Curved Legs	2
F	α	Mesh	1
G	0	Washer	4
Н	8	Nuts	4
1	1	Rod(xs)	4
J	0	Feet	4

Assembly Instruction C42BM



Important: Make sure all parts are available for assembly Follow Instructions steps very carefully



Step 1: Lay large table glass (A) on soft surface
Screw rods (B) into the four plates on the glass and slide cylinders (C) over the rods.

Step 2: Insert curved legs (E) into cross bars (D) as shown in the illustration and align the holes properly.

Step 3: Place leg assembly over rods (B). Ensure the cross bars (D) are seated properly in the groove of the rods.

Step 4: Place mesh basket (F) over rods (B). Place washers (G) and nuts (N) over rods (B) and tighten. Screw feet (J) unto all four rods (I). Screw foot assemblies to curved legs (D) as shown in the illustration.

Warning: Be careful to not over tighten

Step 5: Very carefully turn the table upright

For our most up to date instruction, to request missing, lost, or broken parts, or for any other Customer Service issues, please visit our website at www.walkeredison.com or call us at 877-203-2917.