

ASSEMBLING & INSTALLATION INSTRUCTIONS PRODUCT# 5269 5270 5280

For Flush Mount Ceiling Fixtures

WARNING! SHUT POWER OFF AT FUSE OR CIRCUIT BREAKER.

MOUNTING THE FIXTURE (Fig.1)

1. Shut off the power at the circuit breaker box. Remove old fixture and all hardware from Junction Box.
2. Carefully unpack your new fixture and lay out all the parts on a clear area. Take care not to lose any small parts necessary for installation.
3. Thread the two Studs about 1/4" into the pre-drilled holes in the Mounting plate spaced the same distance apart as the holes in the lamp body.
4. Attach the Mounting plate to the Junction Box with the two Junction Box Screws as shown. The side of the Mounting plate marked "GND" must face out.
5. While holding the lamp body towards the ceiling, connect the electrical wires as Shown in Fig.2, making sure that all wire nuts are secured. You may have to wrap the connections with electrical tape. If your outlet has a ground wire (green or bare copper), connect the fixture ground wire to it. Otherwise connect fixture's ground wire directly to the Mounting plate with the green screw provided. After wires are connected, tuck them carefully inside the Junction Box.
6. Put lamp body onto the junction box, aligning screws on mounting plate with mounting holes in canopy and lock it securely with the ball nuts.
7. Install the light bulbs in accordance with the fixture's specifications.**NOTE: DO NOT EXCEED THE SPECIFIED WATTAGE.**
8. Thread end of pipe nipple (A) into the lamp body's coupling and lock it with the hex nut. Attach the lamella nut(B) to the end pipe nipple(A).
9. Raise the cloth shade(C), plastic shim(D) , glass(E) and plastic shim(F) to the end pipe nipple(A), lock them with the finial(G).

Your installation is now complete. Return power to the junction box and test the fixture.

Fig.1




Fig.2

Fixture Wires	Fixture Wires	Fixture Wires
Black or Smooth	White or Ribbed	Bare Copper (Ground)
House Wires	House Wires	House Wires
Black (Hot)	White (Neutral)	Green or Bare Copper (Ground)

MIN 90°C SUPPLY CONDUCTORS